





30min





PH3




I



II




Ax3



Bx1

Cx5




H= 160 mm

Dx1




H= 160 mm

Ex4



H= 100 mm

Fx15




6x30



PH3


1

Cx2




H= 160 mm

Ex4





H= 100 mm

Fx6




6x30



2

Cx3




H= 160 mm

Dx1





H= 160 mm


Fx9




6x30




3



4



5



6

