








30min




I





II




III



IV




Bx4



H=150 mm

Cx16




5x40




PZ2

Dx4



8x25


Ex1





H=90-140 mm

1


I



IV




Fx4



Ø10



Gx4




8x100

13

III



Hx6




6x40

PH3


2

Fx4



Ø10




Gx4



8x100

13

IV



3

Bx4



H=150 mm


Cx16



5x40



Dx4






8x25

Ex1




H=90-140 mm





4

Hx6







6x40

PH3



5



6

