





KANAPA



PD




X3

PM




X2

B1



X1

B2



X1


G6X25



ŚRUBY W OPARCIU
SCREW IN THE BACKREST

X6

S






X1


O




X1



G6X25



B1



B2

